Photo 1: Outfall at SWMUs 03-012(b) and 03-045(b), outfall located to left of photo

Photo 2: Construction activities at SWMU 03-056(c), preparing for drop inlet installation

Photo 3: Construction activities at SWMU 03-056(c), preparing for drop inlet installation

Photo 4: Preparation for new drop inlet, new outfall location is visible

Photo 5: new outfall location

Photo 6: New outfall location at base of SWMU 03-056(c)

Construction that disturbs affected area triggers a requirement in the permit to restart sampling of the entire required analytical suite in the permit for this site.