Photo 1: LID near parking garage at TA-3

Photo 2: Looking up stream at outfall location for SWMU 03-013(a) and 03-052(f)

Photo 3: Sampler with intake

Photo 4: Sampler intake located in channel

When taking soils data into account, this location may be representative of the affected area.