Photo 1: SWMU 01-003(a) looking back at push pile area (Baileys bridge), note condo on top

Photo 2: LAC outfall pipes draining into canyon

Photo 3: SWMU 01-003(a) sampler location at base of push pile

Soil data indicates that this sampler location is not representative of the affected area. The NMED DOE OB sampler data appears to confirm this.

Photo 4: SWMU 01-003(a) sampler location at base of push pile