Photo 1: Base course berm L00503020009 looking southwest

Photo 2: Base course berm L00503020009 looking southwest

Photo 3: Established vegetation L00502040008 looking northwest

Photo 4: Earthen berm L00503010007 looking east

Photo 5: Sampler identification stake

Photo 6: Upstream face run-on berm

Sampler was at this location, which is directly below the former outfall pipe. This may not be representative of the affected area (effluent channel) downstream to Omega Drive.

Photo 7: Downstream channel view below culvert outlet and mesa top sampler

Photo 8: Downstream view runoff berm