Photo 1: View of berm and spillway looking south

Photo 2: Looking back at former outfall locations behind TA-46

Baseline samples collected at this site (9-13-13) exceeded TALs for copper, silver, PCBs, and hexachlorobenzene. Detects at the detection limit were observed for selenium and cadmium.

Photo 3: Vegetative cover behind TA-46

Photo 4: Sample identifier stake,

Photo 5: Looking back at former outfall locations at TA-46, berms and spillway. Sample location is at base of spillway.