Photo 1: SWMU 33-007(c) concrete pad and backstop area SWMU

Runoff from this SWMU (33-007(c)) is not captured by the current location of the IP sampler for this SMA.

Photo 2: SWMU 33-007(c) backstop area

Runoff from this push pile area where PCB contaminated transformers were located is not captured by the current location of the IP sampler.

Photo 3: SWMU 33-009 push pile in foreground (cinder cone in background)

Photo 4: SWMU 33-004(g) outfall location and 33-007(c) in background

Photo 5: CHQ-SMA-0.5 sampler location

Photo 6: CHQ-SMA-0.5 identifier stake

Photo 7: SWMU 33-009 looking up slope

Photo 8: SWMU 33-009 box on lower slope

Photo 9: Historical signage

Photo 10: SWMU 33-009 vegetated push pile location