

FATAL FACTS



No. 8775-011

Accident Type:	Struck by vehicle
Number of Fatalities	1
Weather Conditions:	Clear
Type of Operation:	Road Construction
Size of Work Crew:	7
Competent Safety Monitor on Site:	No
Safety and Health Program in Effect:	No
Was the Worksite Inspected Regularly:	No
Training and Education Provided:	Yes
Employees Job Titles:	Traffic control flagger
Age & Gender:	46 Female
Experience at this Type of Work:	5 years
Time on Project:	1 week



BRIEF DESCRIPTION OF ACCIDENT

A traffic control flagger was struck by a vehicle driven by an intoxicated driver at an intersection of a construction site.

INSPECTION RESULTS

The inspection revealed the employer maintained a safe working environment and provided employees with adequate training and protective equipment. No citations were issued.

ACCIDENT PREVENTION RECOMMENDATIONS

Employers need to constantly stress the dangers present at roadway construction sites.