

FATAL FACTS



No. 8775-017

Accident Type:	Fall from roof
Number of Fatalities	1
Weather Conditions:	Dry and Calm
Type of Operation:	House repair
Size of Work Crew:	3
Competent Safety Monitor on Site:	No
Safety and Health Program in Effect:	No
Was the Worksite Inspected Regularly:	No
Training and Education Provided:	No
Employees Job Titles:	Laborer
Gender:	Male
Experience at this Type of Work:	Twenty years
Time on Project:	A few days



BRIEF DESCRIPTION OF ACCIDENT

The employee was working on a roof. No witnesses saw the deceased fall to the ground.

INSPECTION RESULTS

The inspection revealed the employer did not have a fall protection plan nor fall protection systems in place. The employer was cited for no fall protection and no training of employees for fall protection.

ACCIDENT PREVENTION RECOMMENDATIONS

The recommendation for preventing this type of accident was to utilize fall protection systems and to conduct training for all employees.