



Petroleum Storage Tank Bureau
2905 Rodeo Park Drive East, Bldg. 1
Santa Fe, NM 87505
Phone: 505.476.4397
Fax: 505.476.4374

Aboveground Storage Tank Systems Inspection Report

Page 1 of 4

Inspection Type: Compliance	Case Number: 38 20250210 0104	Inspection Start Time: 10:15:00 AM	Date: 10-Feb-25
------------------------------------	--------------------------------------	------------------------------------	-----------------

I. Facility Name: Silvas Excavation Inc		Facility ID: 54422	Phone: (505) 758-4562
Address: 1116 Paseo Del Pueblo Norte		City: El Prado	Zip Code: 87529
E-mail: monica@silvasinc.com	Access to property authorized by: Joe Silva		LUST Site: No

II. Owner Name: Silva Joe E		Owner ID: 48028	Phone: (505) 758-4562
Address: PO Box 1011		City: El Prado	State: NM Zip Code: 87529
Contact Name: Joe Silva	E-mail: monica@silvasinc.com		

III. Operator Name: Silva Joe E		Operator ID: P10814	Phone: (505) 758-4562
Address: PO Box 1011		City: El Prado	State: NM Zip Code: 87529
Contact Name: Joe Silva	E-mail: monica@silvasinc.com		

IV. Class A/B Operator Name: None Provided		Phone: N/A	E-mail: N/A
Address: N/A		City: N/A	State: N/A Zip Code: N/A
Who trained Class A/B Operator: N/A			Date Trained: N/A

V. NMED Compliance Officer's Name: Richard Flores		Phone: (505) 470-5370	E-mail: Richard.Flores@env.nm.gov
Address: 2905 Rodeo Park Dr East, Building 1		City: Santa Fe	State: NM Zip Code: 87505

VI. Tank Number	36748						
Size/Capacity:	2,000						
Contents:	B02						
Installation Date:	09/01/2002						
Tank Construction:	A01						
Tank Secondary Containment:	S15						
Piping Construction:	F01,91						
Piping Secondary Containment:	S15						
Other Secondary Containment / Ancillary:	S15						
Corrosion/Cathodic Protection:	C19,20						
Tank Release Detection:	H07						
Piping Release Detection:	G16						
Spill Prevention:	I05						
Overfill Prevention:	I05						
Tank Status & Usage:	U03/TOS						

New Mexico Petroleum Storage Tank Bureau
Aboveground Storage Tank Systems Inspection Checklist

Page 2 of 4

Facility ID Number: 54422

Case Number: 38 20250210 0104

1. Registration (20.5.102 NMAC) and Tank Fees (20.5.103 NMAC)

☐ N/A

A. Are all applicable tanks registered? (20.5.102.200 NMAC)	Yes
B. Current & Valid Registration Certificate on-site? (20.5.102.207 NMAC)	No
C. Owner Mailing address is correct? (20.5.102.208 NMAC)	Unknown
D. Owner in compliance with tank fees. (20.5.103.300 NMAC)	No
E. Notification of transfer of ownership submitted per (20.5.102.201 NMAC)	N/A

2. Operator Training (20.5.104 NMAC)

☒ N/A

3. Operations and Maintenance Plan (20.5.110.1001 NMAC)

☒ N/A

4. Financial Responsibility (20.5.117 NMAC)

☒ N/A

5. Release Prevention

☐ Records Review

☒ N/A

C. Corrosion Protection

☒ N/A

6. Release Detection

☒ N/A

7. Containment

☐ Records Review

☒ N/A

8. Periodic Walk-through Inspections (20.5.110.1008 NMAC)

☒ N/A

9. Tank(s)/Piping/Operations & Maintenance

☒ N/A

10. Notifications and Records

☒ N/A

11. Evidence of a release or spill: Unknown

12. Attachments

☒ Pictures	☐ Site Sketch	☐ Records	☐ Re-training module	☐ Other	☐ Financial Respons.
--	--------------------------------------	----------------------------------	---	--------------------------------	---

13. Comments.

Compliance Inspection:

A) This inspection was conducted on February 10, 2025.

B) The Petroleum Storage Tank Bureau (PSTB) Inspector contacted an individual who currently works with Silvas Excavation through the companies website. The inspector was told the owners would be on site to meet and speak about permanently closing the tank system. When the inspector arrived on site no one was at the property, the inspector proceeded to wait and reached out to the company once more with no response.

C) The inspector proceeded to identify the location of where the tank was previously removed and photograph the area.

D) No evidence of a release was found, although the area is now covered in dirt and debris.

E) Upon review of previous inspector files it has been determined that the tank was removed prior to the inspection conducted on September 25, 2014.

F) No soil samples have since been provided nor a permanent closure form received. As such the tank system remains active in the PSTB system.

G) The Owner on file is listed as a Silva Joe E.

H) The current balance due associated with tank fees including penalties and interest is \$5,320.79.

New Mexico Petroleum Storage Tank Bureau
Aboveground Storage Tank Systems Inspection Checklist

Page 3 of 4

Facility ID Number: 54422 Case Number: 38 20250210 0104

I) To permanently close this tank system soil samples must be provided, a notification of permanent closure be filled out and signed, all associated tank fees, penalties, and interest be paid.

Continuing Enforcement:

I) All violations associated with inspection # 25 20200311 0009 remain in effect.

New Mexico Petroleum Storage Tank Bureau
Aboveground Storage Tank Systems Inspection Checklist

Facility ID Number: 54422 Case Number: 38 20250210 0104

14. Closing Conference and Signatures.

Closing Conference Date: Mar 28, 2025 Closing Conference Time: 10:30:00 AM

Richard Flores
Compliance Officer - Print Name

Richard Flores
Digitally signed by Richard Flores
Date: 2025.03.28 10:17:26 -06'00'
Compliance Officer's Signature

3/28/2025
Date

Silva Joe E
Owner or Representative - Print Name

None Provided
Owner or Representative's Signature

3/28/2025
Date

Owner or Representative - Print Title

monica@silvasinc.com
E-mail Address

Flores, Richard, ENV

From: Microsoft Outlook <MicrosoftExchange329e71ec88ae4615bbc36ab6ce41109e@state.nm.us>
To: monica@silvasinc.com
Sent: Friday, March 28, 2025 10:13 AM
Subject: Undeliverable: Silvas Excavation Inc (FID-54422)



Your message to monica@silvasinc.com couldn't be delivered.

[monica](#) wasn't found at [silvasinc.com](#).

richard.flores

Office 365

monica

Action Required

Recipient

Unknown To address

How to Fix It

The address may be misspelled or may not exist. Try one or more of the following:

- Send the message again following these steps: In Outlook, open this non-delivery report (NDR) and choose **Send Again** from the Report ribbon. In Outlook on the web, select this NDR, then select the link "**To send this message again, click here.**" Then delete and retype the entire recipient address. If prompted with an Auto-Complete List suggestion don't select it. After typing the complete address, click **Send**.
- Contact the recipient (by phone, for example) to check that the address exists and is correct.
- The recipient may have set up email forwarding to an incorrect address. Ask them to check that any forwarding they've set up is working correctly.
- Clear the recipient Auto-Complete List in Outlook or Outlook on the web by following the steps in this article: [Fix email delivery issues for error code 5.1.1 in Office 365](#), and then send the message again. Retype the entire recipient address before selecting **Send**.

If the problem continues, forward this message to your email admin. If you're an email admin, refer to the **More Info for Email Admins** section below.

More Info for Email Admins

Status code: 550 5.1.1

This error occurs because the sender sent a message to an email address outside of Office 365, but the address is incorrect or doesn't exist at the destination domain. The error is reported by the recipient domain's email server, but most often it must be fixed by the person who sent the message. If the steps in the **How to Fix It** section above don't fix the problem, and you're the email admin for the recipient, try one or more of the following:

The email address exists and is correct - Confirm that the recipient address exists, is correct, and is accepting messages.

Synchronize your directories - If you have a hybrid environment and are using directory synchronization make sure the recipient's email address is synced correctly in both Office 365 and in your on-premises directory.

Errant forwarding rule - Check for forwarding rules that aren't behaving as expected. Forwarding can be set up by an admin via mail flow rules or mailbox forwarding address settings, or by the recipient via the Inbox Rules feature.

Mail flow settings and MX records are not correct - Misconfigured mail flow or MX record settings can cause this error. Check your Office 365 mail flow settings to make sure your domain and any mail flow connectors are set up correctly. Also, work with your domain registrar to make sure the MX records for your domain are configured correctly.

For more information and additional tips to fix this issue, see [Fix email delivery issues for error code 550 5.1.1 in Office 365](#).

Original Message Details

Created Date:	3/28/2025 4:13:12 PM
Sender Address:	richard.flores@env.nm.gov
Recipient Address:	monica@silvasinc.com
Subject:	Silvas Excavation Inc (FID-54422)

Error Details

Error: *550-5.1.1 The email account that you tried to reach does not exist. Please try 550-5.1.1 double-checking the recipient's email address for typos or 550-5.1.1 unnecessary spaces. For more information, go to 550 5.1.1 <https://support.google.com/mail/?p=NoSuchUser> ca18e2360f4ac-85e8ffdbab6si244250439f.36 - gsmtip*

Message rejected by: mx.google.com

Notification Details

Sent by: PH8PR09MB9007.namprd09.prod.outlook.com

Message Hops

HOP	TIME (UTC)	FROM	TO	WITH
1	3/28/2025 4:13:12 PM	DM8PR09MB6120.namprd09.prod.outlook.com	DM8PR09MB6120.namprd09.prod.outlook.com	mapi
2	3/28/2025 4:13:12 PM	DM8PR09MB6120.namprd09.prod.outlook.com	PH8PR09MB9007.namprd09.prod.outlook.com	Microsoft SMTP Serv cipher=TLS_ECDHE_

Original Message Headers

ARC-Seal: i=1; a=rsa-sha256; s=arcselector10001; d=microsoft.com; cv=none;

b=wWiltBxh5W5weBiasYxR+n6p++ydhXrk+3SzDpXeA6GRIUy3CfhedlerZP8XQbo+IeV2HKs6en/6Rp0fcel9oyb
+cPLzTiLvHYyiVQb1l0fTMcc4cJoUhNM6y+7jfI4s0RWLGvaNQEyOQK1rTD8GMypgn5RQxwFTml17brnNyeyscfTA
MrygGGCaia7LG+HG4cRLrmg3NUXuEYpWlhOsR3PRaKlsnM90wrRumiYMx0zoL/3LU0/jGkacsw/28z7Cw/fSBB70a
1L79rFd8Bnnv8fAE8xXP4sNEoizMfXa8a1V5bFo4ZKSD+YIDzp6FxnJVVConKCCC0bIdBLS0kwaag==

ARC-Message-Signature: i=1; a=rsa-sha256; c=relaxed/relaxed; d=microsoft.com;
s=arcselector10001;

h=From:Date:Subject:Message-ID:Content-Type:MIME-Version:X-MS-Exchange-AntiSpam-
MessageData-ChunkCount:X-MS-Exchange-AntiSpam-MessageData-0:X-MS-Exchange-AntiSpam-
MessageData-1;

bh=jdvVw8BShvxBOlFdd4600iXwGSdAZSX7SEEpC8EbGJY=;

b=B0gjNlyihSqJZK3W5nZSYO+Y+TpHoVnTbB2AbBGIZl2Iidi0751XltQuwMlWkBXRGEil1e+Y9CaIU0iTHngqRj4
GhWRD0/rvvu1i78ZafwaTNUduWW26/MPzeaR0gvSTNBrYdGNWGF238fJ59rJkU1ITns+e8dL1jM2X1gH6QHbAJ9dN
X+ynDx1UlG1Sw5vRZ0NDK6ZU0Dmy2ocYxrFLK5Q3kb9JUzXqnac/96sLGqN8hcF3qVl3oJeHtyoaAMeItlUwFtnXR
iniRd9ckGguf9Di9yx35qwhCeUSMTitMH0WBFVHFndZZQqicX/ColQCpTgWiE1CNjECr3cS0UmoGA==

ARC-Authentication-Results: i=1; mx.microsoft.com 1; spf=pass

smtp.mailfrom=env.nm.gov; dmarc=pass action=none header.from=env.nm.gov;

dkim=pass header.d=env.nm.gov; arc=none

DKIM-Signature: v=1; a=rsa-sha256; c=relaxed/relaxed; d=env.nm.gov;

s=selector1;

h=From:Date:Subject:Message-ID:Content-Type:MIME-Version:X-MS-Exchange-SenderADCheck;

bh=jdvVw8BShvxBOlFdd4600iXwGSdAZSX7SEEpC8EbGJY=;

b=xEljA4Nbwx7x+xoB1HlccPtX23eg0PvATzJ/+ceE6koVU94dMT8SazwhLLogVH9HlIn1SdkZ1mrQJddln8jKlBf
f0M3xRMDto2w9pPMZWQtK3Yvri+V8ICYjK65L3fAqUGh1WTo2XXyVW8ALxS0Ux9Rejkwuohu53pw0uJP20uTSaR9G
shQ+/A2Ef0AXovvEWESbZ8xrE4nwqVPuPJ5UnG6pNTH0y6J1wLlLgzB6gUZm585JKwofDz5zjiI7nY7TfIyGwjDW7
k09hHs2e6aCngXJAoGwgge+93TE/i4a+LxZR1H4p0C6dXUJER6IS6donM/xF/vXLXdcP+K3F/y0Eg==

Received: from DM8PR09MB6120.namprd09.prod.outlook.com (2603:10b6:5:2ed::14)

by PH8PR09MB9007.namprd09.prod.outlook.com (2603:10b6:510:180::10) with

Microsoft SMTP Server (version=TLS1_2,

cipher=TLS_ECDHE_RSA_WITH_AES_256_GCM_SHA384) id 15.20.8534.44; Fri, 28 Mar

2025 16:13:12 +0000

Received: from DM8PR09MB6120.namprd09.prod.outlook.com

([fe80::1396:6d5b:7ebc:8e67]) by DM8PR09MB6120.namprd09.prod.outlook.com
([fe80::1396:6d5b:7ebc:8e67%6]) with mapi id 15.20.8534.043; Fri, 28 Mar 2025
16:13:12 +0000
From: "Flores, Richard, ENV" <richard.flores@env.nm.gov>
To: "monica@silvasinc.com" <monica@silvasinc.com>
Subject: Silvas Excavation Inc (FID-54422)
Thread-Topic: Silvas Excavation Inc (FID-54422)
Thread-Index: Aduf/DyUxglueELXSGap3SlfplFM3A==
Date: Fri, 28 Mar 2025 16:13:12 +0000
Message-ID:
<DM8PR09MB6120B31B1BEFA1D5839038A3B2A02@DM8PR09MB6120.namprd09.prod.outlook.com>
Accept-Language: en-US
Content-Language: en-US
X-MS-Has-Attach: yes
X-MS-TNEF-Correlator:
authentication-results: dkim=none (message not signed)
header.d=none;dmarc=none action=none header.from=env.nm.gov;
x-ms-publictraffictype: Email
x-ms-traffictypediagnostic: DM8PR09MB6120:EE_|PH8PR09MB9007:EE_
x-ms-office365-filtering-correlation-id: 71da09ab-e67e-4e71-9011-08dd6e13702d
x-ms-exchange-senderadcheck: 1
x-ms-exchange-antispam-relay: 0
x-microsoft-antispam:
BCL:0;ARA:13230040|1800799024|366016|38070700018|4053099003|8096899003;
x-microsoft-antispam-message-info: =?us-
ascii?Q?b9T5qw8CGfmRUOAND5dL5omUpLoLm3V6Hk5P3rc7xQtaAr1RTfFs68Sg2C17?=
=?us-ascii?Q?KqEvFpdA19ghdz+3j04R7ME/Cnq9gAg+BJAQ57c44hZHnMOCqQ2qe1nNCHmY?=
=?us-ascii?Q?xWQ0Tw/wwwwydu/yoYbzTWXV1dXcpj2odx2ui+loiMZpjhjSwnfpA1H6IeXp?=
=?us-ascii?Q?DKq/UNVDH3uFnY/RcBrHb9p9yHoM8dEUFII885G3HHx+iBBVuT4nkBJJ00ml?=
=?us-ascii?Q?sFSsq9gu+74ZhA8Allik1fmp+tjV7afB8G4KTch6GxKbdcvQb+vRfjWkQsZ?=
=?us-ascii?Q?H01D4dedn5z4mXcHk7E6U67hLEt8cE3FFUPpKdbAzXjrBLZYeXSGc3CRtHQ8?=
=?us-ascii?Q?02dzEEgA9lky1u68X5GmfIe/vQUX0E1DJC7cfWMy5cvyk+3RJUDVmrB5e1E6?=
=?us-ascii?Q?b5/jcxyZiKkUafC2bNaksovRfE7Dzv0U0RzPFRTU/wsUZw1Pn7A5IkGk107c?=
=?us-ascii?Q?+Ilk/ey5MqAX0ITIuMV9ncMKYtrGgU5iKXHzLUoH9eHzV07NPtpk3ZBXWSHc?=
=?us-ascii?Q?4eBNadQw9d7sakZmYou6wqsX9D7f2XUtz/8Z0Uql4Y77odnXd9fRGrfQZ0Ur?=
=?us-ascii?Q?rJlMo0SGUnVuV+DKm5uuCsMUCx0/w/V4nfVG4FmJGEep18Z11q6AP94f3jck?=
=?us-ascii?Q?/sQrDPcASZsMpU2mENTboBP/RQUteu2G031E1u35RETBbFuyw75EBcZhwSxU?=
=?us-ascii?Q?0jioPmzv3AeUCXPbf6ihdGrs3ibdoEqk4X0cUj6vRsC00VPRk44gRsUkc8x?=
=?us-ascii?Q?pCAXDSh8BoF/u1wxP3w2Phvj3hRAH4JP/JsLlMFV15txehuQZcZluYctr3js?=
=?us-ascii?Q?ldtQF2hIfziPc0iuiAM0rBSs8Vc9gQk6njzp8u4vWfV+829qm0atix+zL8tG?=
=?us-ascii?Q?ABbkpN1GmGf9Nq6yfIW956mpM6kmTvQ9DnwsdnmCbK79AskDZ9X3pBW5xfEA?=
=?us-ascii?Q?tvNrD6KRoUZrEs/e9R25KERCMKV/Cl3/rRLKSfGwiUdFttGyh2Ydy4PaIDtN?=
=?us-ascii?Q?CjxE1vAe+FyERDHz+xhdCcfurTZgCpyrVFBvF2G/T9gJ+tI4TgDQLsNEckMo?=
=?us-ascii?Q?E9Mx4xtGqOQmRB1nZydogjRG+Bc2xyXLQ+0Rz0800p1xyBA+p66iV0/FQ16U?=
=?us-ascii?Q?/Lg/nxig9lbWfW+4fnZXSNeo9StYAcT0tHeEUJEjVmC0egtcl68tBFcCXRhZ?=
=?us-ascii?Q?UM4AJELLMH1Y9KFRyxkLW07hT3rKXsfDGMSBeM8TM1IgKkNXCLI6Hbdu7U0F?=
=?us-ascii?Q?lgn0pcl00+2J3Wh3a9CB52LcBgMMtT+Tftu8Dv3GzIxpA2TfVRi4DyT6Rqic?=
=?us-ascii?Q?pnopjtV9vLepNf4XgFxn/DLM6/0wFaYdajnk2c1YmIKSoqUkUQJrcJ60P3cw?=

=?us-ascii?Q?cQTA3NSiK28BLtjr1pVztdWnBuwJ?=
x-forefront-antispam-report:
CIP:255.255.255.255;CTRY:;LANG:en;SCL:1;SRV:;IPV:NLI;SFV:NSPM;H:DM8PR09MB6120.namprd09.pr
od.outlook.com;PTR:;CAT:NONE;SFS:(13230040)(1800799024)(366016)(38070700018)(4053099003)(
8096899003);DIR:OUT;SFP:1101;
x-ms-exchange-antispam-messagedata-chunkcount: 1
x-ms-exchange-antispam-messagedata-0: =?us-
ascii?Q?Yq3k9X4J+tBgbMGn9tEphieST3hRahTqx06rYejeDoA4AgEl5zDxQTAjWK8c?=
=?us-ascii?Q?apk0JomtWym66V9vkoU3FD3J3TUXfnN0qFvy6gS8c3atECGwXXsE1LmPR6Jh?=
=?us-ascii?Q?0MwcnFTQncFfx7Z/k+xMAQtj5xjA8b7ZAU+c0vd43+J73ZRUBaP68uDf4+q3?=
=?us-ascii?Q?Xf+g4fdTCg4hQ61rzB1ip+6/X0iifZ0IazCGvcKo2pd+D5F9Jev7JjeKbjvJ?=
=?us-ascii?Q?9iemphUERzW1Aeiehx1L77PQlyi6jPBAowBjAQ7EmNRjKgFGsTpIAW4Zdrre?=
=?us-ascii?Q?F3REWxkfVjH6TLG9mv1y9VkXcqAFGyCETDjPU5raeF6sQEcc2++t0ckW7yop?=
=?us-ascii?Q?efVJyUVBdA3dwZqkWjvtT1gjdWMApfrXAZAenIy+CMJHoMn0P6W5i+d9WzcF?=
=?us-ascii?Q?gzj9VkvKzV1Dd4MALA9PRsJNzX+2SSs0gfW1s8rK1Vm1gNyNqciEc1C/pWv0?=
=?us-ascii?Q?oigvPtaB9JgP4mcLNly5A0dRTiJnpq65+2y2tCJ1FgFtPxP7qbIMt7cXDYP6?=
=?us-ascii?Q?q75JTBw82isXFJkv+RkaW29osfDDH3KLUP7z//006zL60VnvkeKRD/7zCLLs?=
=?us-ascii?Q?26gPrj7Wc6UUXQr5AuYsqmpQ8mZh0ZfL5Aac59vAbV1eD7aghsAt3QdS0lGe?=
=?us-ascii?Q?95KhHjGusus0bZA53Y9YfKBDjiaqRvH5wGETisgMjyHMnYck6s6Ahtov15Mt?=
=?us-ascii?Q?lqm59eZ6vAyrYbD36trea2sNNxH3pcBXkU2CciyrfUSj2jxErG2T+Whyp0j7?=
=?us-ascii?Q?YDoxhKezhIwbf4ME5m4M8PY0/t1Gaw506fzD6Hv/b4frBhq+8hoJV3Unx6T7?=
=?us-ascii?Q?dob2uQyGx7f9lo0kUcHvr0lw25aq2o5Ef0bjgtsDoK+TfhrilVTpT/Nf9bBy?=
=?us-ascii?Q?zDG6mSaE5+AeZ+EqEiRI+62z74+YJiWhWGa+NG0VcjyF7Rem2fDW6io/nK7K?=
=?us-ascii?Q?LGsgsSCA9ocpMkqSEWNkwtPa0wgq0q6h4/FUJEh/aN5P1aFg4WaiOMNzvilv?=
=?us-ascii?Q?rXeshTPOXdX9R4+iSxJpnyL1qr7zdKGLJ5zL4G53i7nwB77UkDGrENAAj+bB?=
=?us-ascii?Q?y6uXxY+g2jWilJXgVs2bFK2maozH0hHvLJGwYnXDQk2w1ChQIbpx1P1R7uph?=
=?us-ascii?Q?kfkWTq068w+xvsF9LJa0TG5mp0MPVGzHIc1M3tLAK9aktehf9FgrSVupSgLB?=
=?us-ascii?Q?H7y5yWF2A/V7TtW3i9enLPxjhNbxVRTCwrmIZ7Amwn4SjHe/Wt8risXzUfN6?=
=?us-ascii?Q?/Il2q3xSmnUbeNxyEEB2pcZ0HeBgx/C+i3F+wwkN/gBpjgPBsTucL0zruco?=
=?us-ascii?Q?pbQL8Y1f8Mfgaq1P3xZexwtmMzSq0y4JbPeZhQBcL5ezQBSi3bMEEEcnCXME?=
=?us-ascii?Q?rGQvzrqkWQv4f62lo9o/JES00XJI7V5tvX0kLj8rCXwgMHGX3BD2jQ359hZX?=
=?us-ascii?Q?4d6w+ipmGntbd+zrDr+w+yacwwOpnbMUG6TmsPYk718IqBdKLxiJ4Fn8RixJ?=
=?us-ascii?Q?3aifsg1+xCnFiyFKrxCvRfyIIqTg9ieSxtQzco0dJCbtBVdEoCLrQAx eo6qU?=
=?us-ascii?Q?1y10Uuy7I4yVcVAYrEJLQiiQLm/xh0VJrju2ePvj?=
Content-Type: multipart/mixed;
 boundary="_006_DM8PR09MB6120B31B1BEFA1D5839038A3B2A02DM8PR09MB6120namp_"
MIME-Version: 1.0
X-OriginatorOrg: env.nm.gov
X-MS-Exchange-CrossTenant-AuthAs: Internal
X-MS-Exchange-CrossTenant-AuthSource: DM8PR09MB6120.namprd09.prod.outlook.com
X-MS-Exchange-CrossTenant-Network-Message-Id: 71da09ab-e67e-4e71-9011-08dd6e13702d
X-MS-Exchange-CrossTenant-originalarrivaltime: 28 Mar 2025 16:13:12.1482
 (UTC)
X-MS-Exchange-CrossTenant-fromentityheader: Hosted
X-MS-Exchange-CrossTenant-id: 04aa6bf4-d436-426f-bfa4-04b7a70e60ff
X-MS-Exchange-Transport-CrossTenantHeadersStamped: PH8PR09MB9007

Facility Name: Silvas Excavation Inc

Facility Number: 54422



Picture Number: 1

Photographer: Richard Flores

Date: Feb 10, 2025 Time: 10:28 AM

Description:

Presumed location of previously removed tank.



Picture Number: 2

Photographer: Richard Flores

Date: Feb 10, 2025 Time: 10:28 AM

Description:

Presumed location of previously removed tank.



Picture Number: 3

Photographer: Richard Flores

Date: Feb 10, 2025 Time: 10:28 AM

Description:

Presumed location of previously removed tank.