

Construction of the new Pajarito Environmental Education Center is at former TA-45, where soils data indicate some contamination.

Photo 1: View east across Acid Canyon at the Pajarito Environmental Education Center (former TA-45)

Photo 2: SWMU 01-002(b)-00 channel within Acid Canyon, looking south towards former outfall area

Photo 3: Gage E055.5

Photo 4: Gage E055.5 and ACID-SMA-2 sampler location

Photo 5: Hill slope below former TA-45

Pipe noted just below construction site of the Pajarito Environmental Education Center - residual contamination could be a concern.

Location of former outfall from an industrial waste line. SWMU 02-002(b)-00.

Photo 6: SWMU 01-002(b)-00 view south at former outfall location