

PERMIT ATTACHMENT E SECURITY PLAN

The following information has been provided to the New Mexico Environment Department, Hazardous Waste Bureau (**HWB**) by Rinchem Company Inc. (**RCI/the Facility**), in accordance with the requirements of the New Mexico Hazardous Waste Management Regulations 20.4.1.500 NMAC, incorporating 40 CFR §264.14.

Security at the RCI Container Storage Facility (**Facility**) shall be accomplished by a security guard, fences surrounding the facility, and warning signs.

Barrier and Means to Control Entrance

RCI employs a number of measures to ensure adequate security in order to assure the protection of the Facility from entry by unauthorized personnel and wildlife.

The Facility has a security alarm system that is connected to each window and door of the warehouse rooms (that comprise the Facility), the fire sprinkler system, the temperature control systems and the pull stations. This monitoring system is manned 24 hours a day by an outside security company. A list of RCI employee names and phone numbers to contact is kept at this monitoring company should an emergency occur.

The entire Facility, including the outside area around the RCI building is maintained in a secure manner. A fence encompasses the entire Facility. The fencing is constructed of 6 foot high, light gauge fabric 2" mesh chain link fence. The fence, gates, the security alarm system, and guards provide adequate access control and shall prevent unknowing entry of unauthorized persons or livestock into the Facility.

All gates shall be maintained in a closed and locked condition during all periods of Facility non-working hours. All critical locks and the alarm codes shall be changed when a Facility employee leaves the company or when a key is lost. During working hours, the gates shall be kept closed or shall be observed by Facility personnel. Access through the main truck loading/unloading gate is blocked by a barrier with a sign informing the truck drivers to check in with the office before entering. The customer service representatives seated immediately inside the office entrance door confirm identification of all visitors and the purpose of their visit. Visitors shall not be allowed in the warehouse without an employee accompanying them. All visitors shall be required to sign a visitors log prior to movement in or around the Facility. Each visitor will be issued a security badge which must be worn while the visitor is on site. The security escort or guide is responsible for ensuring that all visitors comply with these requirements.

Description of Warning Signs

Warning signs shall be posted at all of the Facility gates and several other fence locations around the warehouse in such a manner as to be visible from all angles of approach. The warning signs shall be posted every 50 feet along the perimeter fence of the Facility. These signs shall be legible from a distance of at least 25 feet. These signs shall be printed in both **English** and *Spanish* to read as follows: "**DANGER - UNAUTHORIZED PERSONS KEEP OUT**". Warning signs in Spanish shall be posted next to or below the English warning signs and bear the legend "**PELIGRO - PERSONAS SIN AUTORIZACION NO ENTRADA.**" These signs shall also be posted at the Facility entry points and where the perimeter fence approaches streets or active areas of the Facility.