


# WASTE DISPOSAL PANELS



## Contamination survey to the waste face (Phase 3)

Phase 3 is broken down into multiple entries to address the stay times associated with Level B protective suits. Activity 1 utilizes positive air respirators and 2 pair of coveralls. Activities 2 – 4 begin in Level B protective suits.

- Existing Re-Entry Route
- Continuous Air Monitors
- **Activity 1:** Survey and proceed to airlock between W30 and E140 and to E140/S2000. This allows the team to get close to the overcast (exhaust duct) for the next entry in Level B suits. Establish secondary egress path back to salt hoist via E140.
- **Activity 2:** Survey and proceed to E140/S2520 to evaluate future safe operating base at Waste Handling Lunchroom. Survey to S2750 and shine light to Panel 6 entrance. Survey to W170/S2520.
- **Activity 3:** Establish safe operating base in Waste Handling Lunchroom. Survey from W170/S2520 to Panel 7, entrance to Room 7. A connex and utilities are available at this location.
- **Activity 4:** Identify source at Panel 7 Waste Face or Panel 6.