

AGENDA

**Four Corners Air Quality Task Force Meeting
Power Plant Work Group Session Agenda
Wednesday, August 9, 2006
4:15 – 6:15 pm**

Time	Agenda Item
4:15 – 4:30 pm	Welcome & Introductions Quick round robin and pass sign-in sheet around
4:30 – 4:45 pm	Follow-up Questions from Overview of Mercury Issues, Mark McMillan
4:45 – 5:15 pm	Desert Rock Energy Project Update
5:15 – 6:00 pm	Present Mitigation Option Brainstorm List A & Select Drafting Teams
6:00 – 6:15 pm	Recap of action items and next steps Summarize action items and set agenda for conference calls
6:15 pm	Return to Plenary Work Group Coordinators give a report back on highlights of the session

Power Plants

Work Group Coordinator: Mark Jones; Note taker: Susan Johnson (NPS)
Room: Hovenweep, Conference Cntr.