



DEPARTMENT OF THE AIR FORCE
HEADQUARTERS 377TH AIR BASE WING (AFMC)

Colonel Tom D. Miller
377 ABW/CC
2000 Wyoming Blvd SE
Kirtland AFB NM 87117-5600

30 Dec 13

Mr. Tom Blaine, Manager
RCRA Permits Management Program
Hazardous Waste Bureau (HWB)
New Mexico Environment Department (NMED)
2905 Rodeo Park Road
Santa Fe, New Mexico 87505

Dear Mr. Blaine

Attached please find *Quarterly Pre-Remedy Monitoring and Site Investigation Report for July - September 2013, Bulk Fuels Facility Spill, Solid Waste Management Units ST-106 and SS-111, Kirtland Air Force Base, New Mexico, dated September 2013*. This report has been prepared to summarize ongoing site investigation, remedial, and pre-remedy monitoring activities associated with ST-106 and SS-111.

Please contact Mr. L. Wayne Bitner at (505) 853-3484 or at ludie.bitner@us.af.mil or Mr. Scott Clark at (505) 846-9017 or at scott.clark@us.af.mil if you have questions.

Sincerely

TOM D. MILLER, Colonel, USAF
Commander

Attachment:

Quarterly Pre-Remedy Monitoring & Site Investigation Report for July - September 2013, BFF, December 2013


cc:

NMED-HWB (Kieling, Cobrain, Monts, McDonald, Brandwein) w/attach
NMED-GWQB (Schoepner) w/attach
NMED-PSTB (Reiter) w/attach
NMED-OGC (deSaillan) w/o attach
EPA Region 6 (King) w/o attach
AFCEC-CZRX (Oyelowo) w/o attach
Public Info Repository, AR/IR, and File w/attach

40 CFR 270.11
DOCUMENT CERTIFICATION


**40 CFR 270.11
DOCUMENT CERTIFICATION
DECEMBER 2013**

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision according to a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fines and imprisonment for knowing violations.



TOM D. MILLER, Colonel, USAF
Commander, 377th Air Base Wing

This document has been approved for public release.



KIRTLAND AIR FORCE BASE
377th Air Base Wing Public Affairs

PREFACE

This Quarterly Pre-Remedy Monitoring and Site Investigation Report for July – September 2013 has been prepared by Shaw Environmental & Infrastructure, Inc. (a CB&I company) (Shaw) for the U.S. Army Corps of Engineers (USACE), under Contract No. W912DY-10-D-0014, Delivery Order 0002. It pertains to the Kirtland Air Force Base Bulk Fuels Facility Spill, Solid Waste Management Units ST-106 and SS-111, located in Albuquerque, New Mexico. This Report was prepared in accordance with all applicable federal, state, and local laws and regulations, including the New Mexico Hazardous Waste Act, New Mexico Statutes Annotated 1978, New Mexico Hazardous Waste Management Regulations, Resource Conservation and Recovery Act, and regulatory correspondence between the New Mexico Environment Department Hazardous Waste Bureau and the U.S. Air Force, dated April 2, June 4, August 6, and December 10, 2010.

This work was performed under the authority of USACE Contract No. W912DY-10-D-0014, Delivery Order 0002. All work was conducted from July through September 2013. Mr. John McBee is the USACE Albuquerque District Project Manager; Mr. Wayne Bitner, Jr. is the Kirtland Air Force Base Restoration Section Chief; and Mr. Mike Amdurer is the Shaw Project Manager. This Report was prepared by Diane Agnew and Gary Hecox.



Mike Amdurer
Shaw Environmental & Infrastructure, Inc.
(A CB&I Company)
Project Manager