



SWMU boundary is shown as a very small point and may not be reflective of actual affected area.

Photo 1: SWMU 53-001(b) former storage area



Roof drains are directed onto the SWMU area.

Photo 2: View behind storage area



Photo 3: Current Hazardous waste storage area



Photo 4: Roof drain to right of former storage area



Photo 5: Rock check dam to direct run-off



Photo 6: Rock check dam with former storage area in background



Photo 7: View south of controls (vegetated run-on berm, small basin with spillway) and sampler



Sampler intake may need to be moved to an area where the runoff channel is more defined. It does not appear that this location will collect all stormwater exiting the berm.

Photo 8: Storm water controls with sampler location below berm

S-SMA-3.72



Photo 9: Bottle configuration in ISCO



Photo 10: Sampler