Photo 1: Sampler behind berm / bar ditch.

Photo 2: Looking west at berm along bottom of slope. Outfalls were located towards top of slope.

Photo 3: Berm below former outfall locations.

Photo 4: Vegetated slope below former outfall locations.

Photo 5: looking downslope towards DP canyon drainage.