



NEW MEXICO
ENVIRONMENT DEPARTMENT



Surface Water Quality Bureau

SUSANA MARTINEZ
Governor

JOHN A. SANCHEZ
Lieutenant Governor

Harold Runnels Building, N2050
1190 South St. Francis Drive (87505)
P.O. Box 5469, Santa Fe, NM 87502-5469
Phone (505) 827-0187 Fax (505) 827-0160
www.nmenv.state.nm.us

RYAN FLYNN
Cabinet Secretary

BUTCH TONGATE
Deputy Secretary

ERIKA SCHWENDER
Director
Resource Protection Division

Certified Mail - Return Receipt Requested

March 13, 2014

Ms. Dora M. Romero, School Superintendent
Mora Independent School District
P.O. Box 179
Mora, NM 87732-0179

Re: Mora Independent School District; Minor Industrial; Individual Permit; SIC 8299: NPDES Compliance Evaluation Inspection; NPDES # NM0031097; March 6, 2014

Dear Ms. Romero:

Enclosed please find a copy of the report and checklist for the referenced inspection that the New Mexico Environment Department (NMED) conducted at your facility on behalf of the U.S. Environmental Protection Agency (USEPA). This inspection report will be sent to the USEPA in Dallas for their review. These inspections are used by USEPA to determine compliance with the National Pollutant Discharge Elimination System (NPDES) permitting program in accordance with requirements of the federal Clean Water Act.

Introduction, treatment scheme, and problems noted during this inspection are discussed in the "Further Explanations" section of the inspection report.

You are encouraged to review the inspection report, required to correct any problems noted during the inspection, and advised to modify your operational and/or administrative procedures, as appropriate. If you have comments on or concerns with the basis for the findings in the NMED inspection report, please contact us (see the address below) in writing within 30 days from the date of this letter. Further, you are encouraged to notify in writing both the USEPA and NMED regarding modifications and compliance schedules at the addresses below:

Racquel Douglas
US Environmental Protection Agency, Region VI
Enforcement Branch (6EN-WM)
1445 Ross Avenue
Dallas, Texas 75202-2733

Bruce Yurdin
New Mexico Environment Department
Surface Water Quality Bureau
Point Source Regulation Section
P.O. Box 5469
Santa Fe, New Mexico 87502

Mora Independent School District
March 13, 2014
Page 2

If you have any questions about this inspection report, please contact Daniel Valenta at 505-827-2575 or at daniel.valenta@state.nm.us.

Sincerely,

/s/Bruce Yurdin

Bruce J. Yurdin
Program Manager
Point Source Regulation Section
Surface Water Quality Bureau

cc: Rashida Bowlin, USEPA (6EN-AS) by e-mail
Carol Peters, USEPA (6EN-WM) by e-mail
Brent Larsen, USEPA (6WQ) by e-mail
Racquel Douglas, USEPA (6EN-WM) by e-mail
Gladys Gooden-Jackson, USEPA (6EN-WC) by e-mail
NMED District II, Robert Italiano by e-mail



Form Approved
OMB No. 2040-0003
Approval Expires 7-31-85

NPDES Compliance Inspection Report

Section A: National Data System Coding

Transaction Code	NPDES	yr/mo/day	Inspec. Type	Inspector	Fac Type	
1 <input type="text" value="N"/> 2 <input type="text" value="5"/> 3 <input type="text" value="N"/> <input type="text" value="M"/> <input type="text" value="0"/> <input type="text" value="0"/> <input type="text" value="3"/> <input type="text" value="1"/> <input type="text" value="0"/> <input type="text" value="9"/> <input type="text" value="7"/> 11 12 <input type="text" value="1"/> <input type="text" value="4"/> <input type="text" value="0"/> <input type="text" value="3"/> <input type="text" value="0"/> <input type="text" value="6"/> 17 18 <input type="text" value="C"/> 19 <input type="text" value="S"/> 20 <input type="text" value="2"/>	Remarks					
<input type="text" value="M"/> <input type="text" value="I"/> <input type="text" value="N"/> <input type="text" value="O"/> <input type="text" value="R"/>						
Inspection Work Days	Facility Evaluation Rating	BI	QA	Reserved		
67 <input type="text"/> <input type="text"/> <input type="text"/> 69	70 <input type="text" value="2"/>	71 <input type="text" value="N"/>	72 <input type="text" value="N"/>	73 <input type="text"/>	74 <input type="text"/> 75 <input type="text"/> <input type="text"/> <input type="text"/> <input type="text"/> <input type="text"/> 80	

Section B: Facility Data

Name and Location of Facility Inspected (<i>For industrial users discharging to POTW, also include POTW name and NPDES permit number</i>)	Entry Time /Date 1045 hours / 3-6-2014	Permit Effective Date 9-1-2012
Mora Independent School District Athletic Field, Mora, Mora County, NM: From Albuquerque, take I-25 North to Las Vegas and take Exit 345. Turn left on University Blvd., then right on Hwy 518. Follow Hwy 518 to Mora and the school complex will be on the left side.	Exit Time/Date 1220 hours / 3-6-2014	Permit Expiration Date 8-31-2017
Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s)	Other Facility Data	
Mr. Balthazar Olivas, Maintenance Manager, Mora ISD (575) 447-2811 Mr. Ray Pino, Maintance Assistance, (575)447-5595	GPS: N. 35° 58' 34.26" W -105° 19' 59.13"	
Name, Address of Responsible Official/Title/Phone and Fax Number	SIC: 4971	
Ms. Dora M. Romero, Superintendent, Mora Independent School District PO Box 179, Mora, NM 87732 (575) 387-3106	Contacted Yes <input type="checkbox"/> * <input checked="" type="checkbox"/> No <input type="checkbox"/>	

Section C: Areas Evaluated During Inspection

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

<input type="text" value="S"/>	Permit	<input type="text" value="S"/>	Flow Measurement	<input type="text" value="S"/>	Operations & Maintenance	<input type="text" value="N"/>	CSO/SSO
<input type="text" value="U"/>	Records/Reports	<input type="text" value="U"/>	Self-Monitoring Program	<input type="text" value="N"/>	Sludge Handling/Disposal	<input type="text" value="N"/>	Pollution Prévention
<input type="text" value="S"/>	Facility Site Review	<input type="text" value="N"/>	Compliance Schedules	<input type="text" value="N"/>	Pretreatment	<input type="text" value="N"/>	Multimedia
<input type="text" value="N"/>	Effluent/Receiving Waters	<input type="text" value="N"/>	Laboratory	<input type="text" value="N"/>	Storm Water	<input type="text" value="N"/>	Other:

Section D: Summary of Findings/Comments (Attach additional sheets if necessary)

- Inspectors arrived at the facility at 1045 hours on March 6, 2014. The inspectors conducted an entrance interview with Ms. Dora Romero, School Superintendent, where he made introductions, presented credentials and explained the purpose of the inspection.
- Please see report for further explanations.
- An exit interview to discuss the preliminary findings of the inspection was conducted with Mr. Pino and Ms. Romero at the facility at approximately 1210 hours on March 6, 2014.

Name(s) and Signature(s) of Inspector(s)	Agency/Office/Telephone/Fax	Date
Daniel Valenta /s/Daniel Valenta	505-827-2575	3/13/2014
Signature of Management QA Reviewer	Agency/Office/Phone and Fax Numbers	Date
Sara Holcomb /s/Sara Holcomb	505-827-2798	3/13/2014

SECTION A - PERMIT VERIFICATION

PERMIT SATISFACTORILY ADDRESSES OBSERVATIONS
DETAILS: S M U NA (FURTHER EXPLANATION ATTACHED NO)

1. CORRECT NAME AND MAILING ADDRESS OF PERMITTEE

 Y N NA

2. NOTIFICATION GIVEN TO EPA/STATE OF NEW DIFFERENT OR INCREASED DISCHARGES

 Y N NA

3. NUMBER AND LOCATION OF DISCHARGE POINTS AS DESCRIBED IN PERMIT

 Y N NA

4. ALL DISCHARGES ARE PERMITTED

 Y N NA

SECTION B - RECORDKEEPING AND REPORTING EVALUATION

RECORDS AND REPORTS MAINTAINED AS REQUIRED BY PERMIT.
DETAILS: S M U NA (FURTHER EXPLANATION ATTACHED YES)

1. ANALYTICAL RESULTS CONSISTENT WITH DATA REPORTED ON DMRs.

No discharge has occurred. Y N NA

2. SAMPLING AND ANALYSES DATA ADEQUATE AND INCLUDE.

 S M U NA

a) DATES, TIME(S) AND LOCATION(S) OF SAMPLING

 Y N NA

b) NAME OF INDIVIDUAL PERFORMING SAMPLING

 Y N NA

c) ANALYTICAL METHODS AND TECHNIQUES.

 Y N NA

d) RESULTS OF ANALYSES AND CALIBRATIONS.

 Y N NA

e) DATES AND TIMES OF ANALYSES.

 Y N NA

f) NAME OF PERSON(S) PERFORMING ANALYSES.

 Y N NA

3. LABORATORY EQUIPMENT CALIBRATION AND MAINTENANCE RECORDS ADEQUATE.

 S M U NA

4. PLANT RECORDS INCLUDE SCHEDULES, DATES OF EQUIPMENT MAINTENANCE AND REPAIR.

 S M U NA

5. EFFLUENT LOADINGS CALCULATED USING DAILY EFFLUENT FLOW AND DAILY ANALYTICAL DATA.

 Y N NA

SECTION C - OPERATIONS AND MAINTENANCE

TREATMENT FACILITY PROPERLY OPERATED AND MAINTAINED.
DETAILS: S M U NA (FURTHER EXPLANATION ATTACHED No)

1. TREATMENT UNITS PROPERLY OPERATED.

 S M U NA

2. TREATMENT UNITS PROPERLY MAINTAINED.

 S M U NA

3. STANDBY POWER OR OTHER EQUIVALENT PROVIDED .

 S M U NA

4. ADEQUATE ALARM SYSTEM FOR POWER OR EQUIPMENT FAILURES AVAILABLE.

 S M U NA

5. ALL NEEDED TREATMENT UNITS IN SERVICE

 S M U NA

6. ADEQUATE NUMBER OF QUALIFIED OPERATORS PROVIDED.

 S M U NA7. SPARE PARTS AND SUPPLIES INVENTORY MAINTAINED. **Three groundwater pumps in place if one should fail.** S M U NA

8. OPERATION AND MAINTENANCE MANUAL AVAILABLE.

 Y N NA

STANDARD OPERATING PROCEDURES AND SCHEDULES ESTABLISHED.

 Y N NA

PROCEDURES FOR EMERGENCY TREATMENT CONTROL ESTABLISHED.

 Y N NA

SECTION C - OPERATIONS AND MAINTENANCE (CONT'D)

9. HAVE BYPASSES/OVERFLOWS OCCURRED AT THE PLANT OR IN THE COLLECTION SYSTEM IN THE LAST YEAR? Y N NA
 IF SO, HAS THE REGULATORY AGENCY BEEN NOTIFIED? Y N NA
 HAS CORRECTIVE ACTION BEEN TAKEN TO PREVENT ADDITIONAL BYPASSES/OVERFLOWS? Y N NA
10. HAVE ANY HYDRAULIC OVERLOADS OCCURRED AT THE TREATMENT PLANT? Y N NA
 IF SO, DID PERMIT VIOLATIONS OCCUR AS A RESULT? Y N NA

SECTION D - SELF-MONITORING

PERMITTEE SELF-MONITORING MEETS PERMIT REQUIREMENTS. S M U NA (FURTHER EXPLANATION ATTACHED Yes).
 DETAILS: **No discharges have occurred.**

1. SAMPLES TAKEN AT SITE(S) SPECIFIED IN PERMIT. Y N NA
2. LOCATIONS ADEQUATE FOR REPRESENTATIVE SAMPLES. Y N NA
3. FLOW PROPORTIONED SAMPLES OBTAINED WHEN REQUIRED BY PERMIT. Y N NA
4. SAMPLING AND ANALYSES COMPLETED ON PARAMETERS SPECIFIED IN PERMIT. Y N NA
5. SAMPLING AND ANALYSES PERFORMED AT FREQUENCY SPECIFIED IN PERMIT. Y N NA
6. SAMPLE COLLECTION PROCEDURES ADEQUATE Y N NA
- a) SAMPLES REFRIGERATED DURING COMPOSITING. Y N NA
- b) PROPER PRESERVATION TECHNIQUES USED. Y N NA
- c) CONTAINERS AND SAMPLE HOLDING TIMES CONFORM TO 40 CFR 136.3. Y N NA
7. IF MONITORING AND ANALYSES ARE PERFORMED MORE OFTEN THAN REQUIRED BY PERMIT, ARE THE RESULTS REPORTED IN PERMITTEE'S SELF-MONITORING REPORT? Y N NA

SECTION E - FLOW MEASUREMENT

PERMITTEE FLOW MEASUREMENT MEETS PERMIT REQUIREMENTS. S M U NA (FURTHER EXPLANATION ATTACHED NO)
 DETAILS:

1. PRIMARY FLOW MEASUREMENT DEVICE PROPERLY INSTALLED AND MAINTAINED. Y N NA
 TYPE OF DEVICE **Discharge is measured at each of the three wells by inline totalizer, recorded monthly.**
2. FLOW MEASURED AT EACH OUTFALL AS REQUIRED. Y N NA
3. SECONDARY INSTRUMENTS (TOTALIZERS, RECORDERS, ETC.) PROPERLY OPERATED AND MAINTAINED. Y N NA
4. CALIBRATION FREQUENCY ADEQUATE. **No water to discharge.** Y N NA
 RECORDS MAINTAINED OF CALIBRATION PROCEDURES. Y N NA
 CALIBRATION CHECKS DONE TO ASSURE CONTINUED COMPLIANCE. Y N NA
5. FLOW ENTERING DEVICE WELL DISTRIBUTED ACROSS THE CHANNEL AND FREE OF TURBULENCE. Y N NA
6. HEAD MEASURED AT PROPER LOCATION. Y N NA
7. FLOW MEASUREMENT EQUIPMENT ADEQUATE TO HANDLE EXPECTED RANGE OF FLOW RATES. Y N NA

SECTION F - LABORATORY

PERMITTEE LABORATORY PROCEDURES MEET PERMIT REQUIREMENTS. S M U NA (FURTHER EXPLANATION ATTACHED NO)
 DETAILS:

- No discharge to take a sample from.**
1. EPA APPROVED ANALYTICAL PROCEDURES USED (40 CFR 136.3 FOR LIQUIDS, 503.8(b) FOR SLUDGES) Y N NA

SECTION F - LABORATORY (CONT'D)

2. IF ALTERNATIVE ANALYTICAL PROCEDURES ARE USED, PROPER APPROVAL HAS BEEN OBTAINED Y N NA
3. SATISFACTORY CALIBRATION AND MAINTENANCE OF INSTRUMENTS AND EQUIPMENT. S M U NA
4. QUALITY CONTROL PROCEDURES ADEQUATE. S M U NA
5. DUPLICATE SAMPLES ARE ANALYZED. 0 % OF THE TIME. Y N NA
6. SPIKED SAMPLES ARE ANALYZED. % OF THE TIME. Y N NA
7. COMMERCIAL LABORATORY USED. **Facility is working on contracting out sampling requirements.** Y N NA

LAB NAME

LAB ADDRESS

PARAMETERS PERFORMED

SECTION G - EFFLUENT/RECEIVING WATERS OBSERVATIONS. S M U NA (FURTHER EXPLANATION ATTACHED YES).

OUTFALL NO.	OIL SHEEN	GREASE	TURBIDITY	VISIBLE FOAM	FLOAT SOL.	COLOR	OTHER
001	No Discharge						

RECEIVING WATER OBSERVATIONS

SECTION H - SLUDGE DISPOSAL

SLUDGE DISPOSAL MEETS PERMIT REQUIREMENTS. S M U NA (FURTHER EXPLANATION ATTACHED NO).

DETAILS:

1. SLUDGE MANAGEMENT ADEQUATE TO MAINTAIN EFFLUENT QUALITY. S M U NA
2. SLUDGE RECORDS MAINTAINED AS REQUIRED BY 40 CFR 503. S M U NA
3. FOR LAND APPLIED SLUDGE, TYPE OF LAND APPLIED TO: _____ (e.g., FOREST, AGRICULTURAL, PUBLIC CONTACT SITE)

SECTION I - SAMPLING INSPECTION PROCEDURES (FURTHER EXPLANATION ATTACHED).

1. SAMPLES OBTAINED THIS INSPECTION. Y N NA
2. TYPE OF SAMPLE OBTAINED
GRAB _____ COMPOSITE SAMPLE _____ METHOD _____ FREQUENCY _____
3. SAMPLES PRESERVED. Y N NA
4. FLOW PROPORTIONED SAMPLES OBTAINED. Y N NA
5. SAMPLE OBTAINED FROM FACILITY'S SAMPLING DEVICE. Y N NA
6. SAMPLE REPRESENTATIVE OF VOLUME AND MATURE OF DISCHARGE. Y N NA
7. SAMPLE SPLIT WITH PERMITTEE. Y N NA
8. CHAIN-OF-CUSTODY PROCEDURES EMPLOYED. Y N NA
9. SAMPLES COLLECTED IN ACCORDANCE WITH PERMIT. Y N NA

**Compliance Evaluation Inspection
Mora Independent School District
NPDES Permit No. NM0031097
March 6, 2014**

Introduction

On March 6, 2014, Daniel Valenta and Erin Trujillo of the New Mexico Environment Department (NMED), Surface Water Quality Bureau (SWQB) conducted a Compliance Evaluation Inspection (CEI) at the Mora Independent School District Athletic Field Project. The Athletic Field Project has an intermittent flow design (the system is only used when the ground water table is high) and is classified as a minor industrial discharger under the Federal Clean Water Act, Section 402, of the National Pollutant Discharge Elimination System (NPDES) permit program. It is assigned NPDES permit number NM0031097. This permit regulates the facilities discharges to the Mora River in the Canadian Basin in Segment 20.6.4.309 according to the *State of New Mexico Standards for Interstate and Intrastate Surface Waters, 20.6.4 NMAC*. This segment includes the designated uses of domestic water supply, irrigation, high quality coldwater aquatic life, livestock watering, wildlife habitat, primary contact, and public water supply on the Cimarron river upstream from Cimarron and on the perennial reaches of Rayado creek and its tributaries.

The NMED performs a certain number of CEIs for the U.S. Environmental Protection Agency (USEPA), Region VI, under the NPDES permit program, in accordance with the Federal Clean Water Act. USEPA uses these inspections to determine compliance with the NPDES permit program. This inspection report is based on information provided by the permittee's representatives, observations made by the NMED inspector, and records and reports kept by the permittee and/or NMED.

Upon arrival at the facility at 1045 hours on March 6, 2014, the inspectors conducted an entrance interview with Ms. Dora Romero, School Superintendent, Mr. Ray Pino, Maintenance Assistant, and by phone Mr. Balthazar Olivas, Maintenance Manager, where they made introductions, presented credentials and explained the purpose of the inspection. Mr. Pino conducted a tour of the facility. An exit interview was conducted with Ms. Romero and Mr. Pino at the facility at approximately 1210 hours on March 6, 2014 to present the preliminary findings of the inspection.

Treatment Scheme

The Mora High School Athletic Field is located in an area where the ground water table is typically high during the spring runoff season. Historically, this would cause issues with standing water in the field. In 2012, a project was started to resolve the standing water issue.

Three ground water pumps (with Mag Meter flow meters) were installed at the athletic field to pump groundwater to the Mora River when the ground water level reached 21 feet of the surface. Their most recent discharge was for 3-4 weeks in May-June 2012. The NPDES permit for this facility was issued in September 2012, there has not been a discharge since due to the drought conditions in the area.

**Compliance Evaluation Inspection
Mora Independent School District
NPDES Permit No. NM0031097
March 6, 2014**

Further Explanations

Section B – Recordkeeping and Reporting Evaluation – Overall rating of *Unsatisfactory*

The permit states in Part I.C:

Monitoring results must be reported either using the electronic or paper Discharge Monitoring Report (DMR) approved formats to EPA. If using paper DMR forms, the report shall also be sent to NMED and shall be submitted quarterly. Each quarterly submittal shall include separate forms for each month of the reporting period. See Part III, D.4 of the permit.

1. *Reporting periods shall end on the last day of the months March, June, September and December.*
2. *The permittee is required to submit regular quarterly reports as described above postmarked no later than the 28th day of the month following each reporting period.*

Findings for Recordkeeping and Reporting:

The facility representatives indicated to the inspectors that they were aware that they had been issued an NPDES permit and were aware of some reporting requirements however had not pursued the issue further. **This is a repeat finding of the July 2, 2013 inspection.** Consequently, no Discharge Monitoring Reports had been submitted to EPA or NMED. The inspector also discussed the availability of the NetDMR system with Ms. Romero. Details of the system and how to sign up can be found at https://netdmr.epa.gov/netdmr/public/getting_started.htm

Section D – Self Monitoring Evaluation – overall rating of *Unsatisfactory*

The permit states in Part I.A.1:

EFFLUENT	DISCHARGE LIMITATIONS		MONITORING	
	Standard Units		MEASURENT FREQUEN	SAMPLE
POLLUTANT	MINIMUM	MAXIMUM	Once/Month	Gra
pH	6	8		

EF FL POLLUTANT	DISCHARGE LIMITATIONS				MONITORING REQUIREMENTS	
	lbs/day, unless		mg/l, unless noted (*2)		MEASUM FREQU	SAMPLE TYPE
	30-DAY AVG	DAILY MAX	30-DAY AVG	DAILY MAX		
Flow	Report MGD	Report	*	*	Daily	Measure
TSS (*3)	Report	Report	Report	Report	Once/Month	Grab
TSS (*4)	318	Report	8	Report	Once/Month	Grab
TDS (*3)	Report	Report	Report	Report	Once/Month	Grab
TDS (*4)	12,970	Report	3	Report	Once/Month	Grab

**Compliance Evaluation Inspection
Mora Independent School District
NPDES Permit No. NM0031097
March 6, 2014**

EFFLUENT	DISCHARGE MONITORING		MONITORING	
	30-DAY AVG	48-HOUR MINIMUM	MEASUREMENT FREQUENCY	SAMPLE
Whole Effluent Toxicity Testing	Report	Report	Once (*6, 7)	24-Hour
Daphnia pulex	Report	Report	Once (*6, 7)	24-Hour
Pimephales promelas	Report	Report	Once (*6, 7)	24-Hour

And, the permit states in Part I.B.1:

1. *TSS and TDS:*

The permittee shall comply with the following schedule of activities for the attainment of state water quality standards-based interim effluent limitations for TSS and TDS, at Final Outfall 001.

- a. Develop control options, if needed;*
- b. Evaluate and select control mechanisms;*
- c. Implement corrective action; and*
- d. Attain interim effluent limitations no later than two (2) years from the permit effective date (PED).*

The permittee shall submit quarterly progress reports, to both EPA and NMED, in accordance with the following schedule. The requirement to submit quarterly progress reports shall expire two (2) years from the PED. No later than 14-days after the date compliance with the TDS and TSS limits have been met; the permittee shall submit a written final report to both the EPA and State, stating that compliance has been completed. If at any time during the two (2) years compliance period the permittee determines that full compliance will not be met within the time allowed, a separate report shall be sent to both EPA and the State stating the explanation for this delay and proposed remedial actions. The compliance schedules shown above shall report progress reports (sic) according to the following schedule:

PROGRESS REPORT DATES

- January 1*
- April 1*
- July 1*
- October 1*

Findings for Self-Monitoring Evaluation: Unsatisfactory

As mentioned earlier in this report, the permittee's representatives were aware that an NPDES permit had been issued for the ground water purge discharge. The facility has not discharged thus no samples were taken or analyzed per the above requirements. However DMR's and Progress Reports must be submitted indicating no discharge has occurred. No preparations have been put in place to have samples taken if and when a discharge does occur. Once the groundwater level rises to 21 feet of the surface the pumps will activate with no warning and a discharge will occur. **This is a repeat finding of the July 2, 2013 inspection.**

NMED/SWQB

Official Photograph Log

Photo # 1

Photographer: Daniel Valenta	Date: 4/6/2014	Time: 1148 hours
City/County: Mora, Mora County		
Location: North of Mora High School on unnamed road that crosses the Mora River, facing south.		
Subject: Discharge outfall 001 if the groundwater pumps engaged.		



NMED/SWQB

Official Photograph Log

Photo # 2

Photographer: Daniel Valenta	Date: 4/6/2014	Time: 1149 hours
City/County: Mora, Mora County		
Location: North of Mora High School on unnamed road that crosses the Mora River, facing west.		
Subject: Mora river upstream of outfall 001.		



NMED/SWQB

Official Photograph Log

Photo # 3

Photographer: Daniel Valenta	Date: 4/6/2014	Time: 1310 hours
City/County: Mora, Mora County		
Location: Mora High School track field, facing south.		
Subject: Groundwater well and generator next to field track.		

