

**List of Reports Available for Review and Copying at
Fed Ex Office, Print & Ship Center
Linda Beaty, Customer Service Specialist
730 Saint Michael's Drive, Suite 3E
Santa Fe, NM 87505
Telephone (505) 473-7303
Fax (505) 473-2113
linda.beaty@fedex.com**

210 & 218 Montezuma Avenue		
#	Date	Title
M-1	12/21/98	Environmental Site Assessment
M-2	02/19/99	Environmental Site Assessment
M-3	10/16/03	Site Reconnaissance, Vapor Survey and Groundwater Monitoring
M-4	05/20/04	Secondary Investigation Report
M-5	04/15/05	Bail-down Test Results
M-6	03/31/06	Secondary Investigation Report
M-7	05/14/09	Vapor surveys – 210 & 218 Montezuma Avenue and 328 Galisteo
M-8	06/10/09	Fourth Quarter Groundwater Monitoring Report
M-9	07/07/09	Geophysical Investigation Report
M-10	08/10/09	SVE and Monitor Well Installation and Groundwater Monitoring
M-11	08/25/09	Monitor Well Installation and Groundwater Monitoring

Capitol 66		
#	Date	Title
C-1	03/01/91	Investigation of Gasoline Contamination
C-2	08/21/91	Environmental Site Assessment
C-3	04/28/92	Modified Reclamation Proposal
C-4	05/17/93	VES Test Results
C-5	04/28/98	Semi-Annual Monitoring Report
C-6	01/04/99	Confirmation Soil Boring Report
C-7	07/03/02	Quarterly Groundwater Monitoring Report
C-8	06/27/07	1 st Quarter Monitoring, NAPL Recovery & Report
C-9	04/09/08	4 th Quarter Monitoring, NAPL Recovery & Report
C-10	04/20/09	Hall Environmental Analysis Laboratory Report

Santa Fe County Judicial Complex		
#	Date	Title
S-1	04/30/09	Santa Fe County Judicial Complex Request for Information Submittal CD of RT Hicks Pumping Test Data, September/October 2008 (back inside cover)
S-2	06/16/09	Additional Site Investigation Report
S-3	07/27/09	New Mexico Environment Department Request for Additional Information
S-4	08/13/09	LNAPL Bail-Down Test Results and Preliminary LNAPL Volume Estimate
S-5	08/21/09	Light Non-Aqueous Phase Liquid (LNAPL) Sample Analytical Results
S-6	08/25/09	August 2009 Fluid Level Measurements
S-7	08/25/09	Fluid Level Graphs