

**New Mexico Environment Department – Petroleum Storage Tank Bureau  
Public Record on Underground Storage Tank (USTs)**

**Public Record Date Posted: November 7, 2012**

**General Information**

Total Number of UST facilities	1249
Total Number of USTs	3367

**Summary Information for On-site Inspections**

Number of UST facilities Inspected	687	
Inspection Period Dates	From: 10/1/2011	To: 9/30/2012
Percent Compliance (Combined Measures <sup>1</sup> )	70%	

**Summary Information for Releases**

Number of Confirmed UST Releases	21	
Release Reporting Period Dates	From: 10/1/2011	To: 9/30/2012

**Summary Information for Release Sources and Causes**

Source			Cause													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	# <sup>2</sup>	% <sup>2</sup>	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	5	24					1	5	4	19						
Piping	5	24							1	5	1	5	1	5	2	10
Dispenser																
STP <sup>3</sup> Area																
Delivery Problem	4	19	2	9	2	9										
Flex Connector	3	14					2	9			1	5				
Other	4	19													4	19
Totals	21	100	2	9	2	9	3	14	5	24	2	10	1	5	6	29

Notes: (1) Number and percent of underground storage tank (UST) facilities in significant operational compliance with release prevention and release detection regulations of the Petroleum Storage Tank regulations.

(2) # = Number, % = percent of total number

(3) STP = Submersible Turbine Pump

Site specific information on confirmed releases can be obtained by making a public information request to:

Melissa Mascareñas  
Inspection of Public Records Officer  
1190 St. Francis Drive, Suite N-4050 Santa Fe, NM 87505  
Or fax: (505) 827-1628 Or email: melissa.mascarenas@state.nm.us