

**New Mexico Environment Department – Petroleum Storage Tank Bureau  
Public Record on Underground Storage Tank (USTs)**

**Public Record Date Posted: December 9, 2010**

**General Information**

Total Number of UST facilities	1261
Total Number of USTs	3442

**Summary Information for On-site Inspections**

Number of UST facilities Inspected	842	
Inspection Period Dates	From: 10/1/2009	To: 9/30/2010
Percent Compliance (Combined Measures <sup>1</sup> )	56%	

**Summary Information for Releases**

Number of Confirmed UST Releases	17	
Release Reporting Period Dates	From: 10/1/2009	To: 9/30/2010

**Summary Information for Release Sources and Causes**

Source			Cause													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	# <sup>2</sup>	% <sup>2</sup>	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	6	34					1	6	2	12					3	18
Piping																
Dispenser	1	6													1	6
STP <sup>3</sup> Area	4	24					4	24								
Delivery Problem	2	12			2	12										
Flex Connector	2	12					1	6							1	6
Other	2	12													2	12
Totals	17	100			2	12	6	34	2	12					7	42

Notes: (1) Number and percent of underground storage tank (UST) facilities in significant operational compliance with release prevention and release detection regulations of the Petroleum Storage Tank regulations.

(2) # = Number, % = percent of total number

(3) STP = Submersible Turbine Pump

Site specific information on confirmed releases can be obtained by making a public information request to:  
Melissa Mascareñas  
Inspection of Public Records Officer  
1190 St. Francis Drive, Suite N-4050 Santa Fe, NM 87505  
Or fax: (505) 827-1628 Or email: melissa.mascarenas@state.nm.us