

Administrative Record (technical records)

AQS, 2017a. Revised Technical Review Comments on the Final Resource Conservation and Recovery Act Facility Investigation Report Asphalt Dump Area (OT-573), Kirtland Air Force Base, March 2014. May.

AQS, 2017b. Revised Technical Review Comments on the Final Resource Conservation and Recovery Act Facility Investigation Report Building 57001 (OT-572), Kirtland Air Force Base, March 2014. May.

AQS, 2017c. Revised Technical Review Comments on the Final Resource Conservation and Recovery Act Facility Investigation Report Transient Alert Pad (OT-575), Kirtland Air Force Base, March 2014. May.

AQS, 2017d. Revised Technical Review Comments on the Final Resource Conservation and Recovery Act Facility Investigation Report Zia Park (CW-571), Kirtland Air Force Base, March 2014. May.

KAFB, 2004. NMED, March 2, 2004, Request for Supplemental Information Response Installation Restoration Program No Further Action Report for Active SWMUs 8-5, 8-6, 6-14, 8-26, 8-28, 8-29, 8-31, 8-41, 8-47, 8-55, 9-14, 10-1, 10-7, ST-273, and ST-340 Addendum, May 28.

KAFB, 2006. Memorandum to NMED from KAFB, *Subject: Response to your letter dated August 26, 2004 "Response to Request for Supplemental Information: Installation Restoration Program No Further Action Report for Active Soil Waste Management Units 8-5, 8-6, 6-14, 8-26, 8-28, 8-29, 8-31, 8-41, 8-47, 8-55, 9-14, 10-1, 10-7, ST-273, and ST-340 (Dated June 2000) May 2004, KAFB ID # NM9570024423."* April.

NMED, 1997. *"Request for Supplemental Information: Background Concentrations Report, SNL/KAFB,"* letter to M.J. Zamorski, Acting Area Manager, Kirtland Area Office, U.S. Department of Energy, from R.S. Dinwiddie, Ph.D., Manager RCRA Permits Program, Hazardous and Radioactive Materials Bureau, New Mexico Environment Department. September.

NMED, 2010. *Hazardous Waste Treatment Facility Operating Permit EPA ID No. NM9570024423, issued to the United States Air Force for the Open Detonation Unit located at Kirtland Air Force Base, Bernalillo County, New Mexico.* Hazardous Waste Bureau. July.

NMED, 2012. *Risk Assessment Guidance for Site Investigation and Remediation, Volume 1, Tier 1: Soil Screening Guidance Technical Background Document, Table A-1, NMED Soil Screening Levels.* Hazardous Waste Bureau and Ground Water Quality Bureau Voluntary Remediation Program. New Mexico Environment Department, Santa Fe, New Mexico. February.

NMED, 2017. *Risk Assessment Guidance for Site Investigations and Remediation, Volume I Soil Screening Guidance for Human Health Risk Assessments.* Hazardous Waste Bureau and Ground Water Quality Bureau Voluntary Remediation Program. New Mexico Environment Department, Santa Fe, New Mexico. February.

NMED, 2017. *Risk Assessment Guidance for Site Investigations and Remediation, Volume II Soil Screening Guidance for Ecological Risk Assessments.* Hazardous Waste Bureau and Ground Water Quality Bureau Voluntary Remediation Program. New Mexico Environment Department, Santa Fe, New Mexico. February.

Shaw, 2012a. *Final SWMU Assessment Report Building 57001 (OT-573)*. Kirtland Air Force Base, New Mexico. March.

Shaw, 2012b. *Final SWMU Assessment Report Transient Alert Pad (SS-C575)*. Kirtland Air Force Base, New Mexico. March.

Shaw, 2012c. *Final SWMU Assessment Report Zia Park (CS-C571) and Asphalt Dump Area (OT-C573)*. Kirtland Air Force Base, New Mexico. March.

Shaw, 2012d. *Final Accelerated Corrective Measures Work Plan Asphalt Dump Area (OT-C573)*. Kirtland Air Force Base, New Mexico. March.

USAF, 2014a. *Final Resource Conservation and Recovery Act Facility Investigation Report – Zia Park (CW-571)*. U.S. Air Force, Kirtland Air Force Base, New Mexico. March.

USAF, 2014b. *Final Resource Conservation and Recovery Act Facility Investigation Report – Building 57001 (OT-572)*. U.S. Air Force, Kirtland Air Force Base, New Mexico. March.

USAF, 2014c. *Final Resource Conservation and Recovery Act Facility Investigation Report - Asphalt Dump Area (OT-573)*. U.S. Air Force, Kirtland Air Force Base, New Mexico. March.

USAF, 2014d. *Final Resource Conservation and Recovery Act Facility Investigation Report – Transient Alert Pad (SS-575)*. U.S. Air Force, Kirtland Air Force Base, New Mexico. March.

USAF, 2016. *Final Corrective Action Complete Proposals Without Controls Status for Sites CW-571, OT 572, and OT-573; With Controls Status for Site SS-575, April 2016*. U.S. Air Force, Kirtland Air Force Base, New Mexico. June.