


# WSTF Waste Accumulation Areas

- 90 Day
- Permitted Waste Unit

Satellite Accumulation Area



November 2008



AREA NAME	STATUS	FAC AREA	DESCRIPTION	TYPE	ITEMS	2ND CONT
GSA-1	a	100	West of Building 151 - Vehicle Service Garage	sa	used oil and solvent/contaminated rags	Yes
150 DSF	a	100	Drum Storage Facility 5 of Building 150 under shed	sa	used oil, used batteries, fuel, used solvents	Yes
FAC 156	a	100	Building 156 - Outside on the North end	sa	used oil, oily sludge/slop, antiseptic, fuel filters	Yes
113 FAC	a	100	Building 158 - Outside on SE side near clearing pe	sa	city sludge	Yes
PAINT SH	a	100	Building 158 - Outside near NW corner	sa	rags with solvent	No
MAC SHOP	a	100	Building 113 - Outside near SW corner, west side	sa	used oil, waste coolant, contaminated spillage	Yes
M&C 121	a	100	Building 121 - Outside near SE corner, south side	sa	refrigerant coolant, used batteries, contaminated rags	Yes
DOME ACP	a	100	By Dome outside Building 159	sa	waste paint	No
158W	a	100	Flammable coolant on West side of Building 158	sa	paint and related materials	Yes
158NE	a	100	NE corner of Building 158 by fence	sa	paint waste and related materials	Yes
GSA-2	a	100	South of Building 151, next to Morgan building	sa	contaminated spillage, spent batteries	Yes
CSU	a	100	Building 181	90 day	slush waste (permitted)	Yes
121 FB	a	100	Next to Bldg. 121, Southeast corner	sa	fluorescent tubes	Yes
156 UW	a	100	Building 156, heavy equipment yard, East side	sa	spent batteries	Yes
MAC RAGS	a	100	Building 113 - Inside on west wall	sa	contaminated machine shop rags	No
COMMO	a	100	Building 119 - Outside east wall	sa	spent batteries	No
156 SH	a	100	Building 156 - Inside	sa	contaminated shop rags	No
158NE-A	a	100	NE corner of Building 158 by fence	sa	paint waste and related material	No
SOFT COL	a	200	Alley between Buildings 200 & 201	90 day	fuel and oil contaminated soft goods	No
VAC LAB	a	200	Alley between Buildings 200 & 201, Near T-242	sa	contaminated vacuum pump oil, contaminated refuse	No
CLN OUT	a	200	West wall of LAB CON Highbay	sa	used oil, contaminated refuse, contaminated vacuum pump oil	Yes
LAB CON	a	200	Fenced area outside of Clean Room LAB CON	sa	waste isotopic solvents	No
200 MECHANICAL	a	200	200 Area mechanical room, E side N Highway	sa	used oil, contaminated rags	No
BAT COL	a	200	Building 200 - Room 137 against North wall	sa	contaminated shop rags	No
CHEM 42	a	200	Building 200 - Room 136 under hood 42	sa	waste organics	No
CHEM 39	a	200	Building 200 - Room 126 under hood 39	sa	waste organics	No
CHEM 4	a	200	Building 203 - Room 124, under fume hood	sa	waste organics	No
MET 32	a	200	Building 203 - Room 121, under hood # 32	sa	waste organics	No
ELEC CAL	a	200	Building 203 - Room 110 by Autodieler	sa	spent batteries	Yes
METAL	a	200	Building 203 - Room 148	sa	waste organics	No
CAL LAB	a	200	Building 203 - Room 136, North East corner	sa	waste mercury and mercury contaminated materials	No
FAF 1	a	200	N Highway - Room 162, West wall under on hood	sa	decon water with fuel, fuel/solvent contaminated soft goods	No
ETU	a	200	200 Area	90 day	slush waste (permitted)	Yes
200 EVAP	a	200	North Side of portable building at the ETU	sa	waste contaminated soft goods	No
NW 201	a	200	NW corner of alley between Buildings 200 and 201	sa	organic wastewater	No
CSFH	a	200	Under fume hood in Components Services Dept.	sa	waste passivation fluid and waste acid matrix	No
CCSBM	a	200	Outside Components Services Highbay by fence	sa	waste blast media	No
200 MET	a	200	Outside Room 136 of Bldg. 203, in alley	sa	waste fuel, waste metals standards, waste film	No
CCSB	a	200	Outside Components Services Highbay, south of CCSB	sa	fuel and oil contaminated soft goods	No
NDMA	a	200	Building 203, Room 124	90 day	NDMA contaminated soft goods	No
CTF RAGS	a	200	West side of North Highway, near door	sa	solvent contaminated rags	No
272	a	270	Building 272 - East wall	sa	solvent/contaminated rags	No
SP ST	a	300	East of HCU on secondary containment pad	sa	solvent and rags	No
300 DECON	a	300	Between Fuel and Ox RStUs	90 day	decon water with oxidizer	No
300 OX BAR	a	300	Decon sink between ox and fuel RStUs	90 day	decon water with oxidizer	Yes
300 FUEL BAR	a	300	Decon sink between the ox and fuel RStUs	90 day	decon water with fuel	Yes
300 90 DAY	a	300	Near the 300 Area decon strike	90 day	decon water with fuel	Yes
NT01	a	300	Near front of NE corner TS 328, mobile	90 day	decon water with oxidizer	No
NT02	a	300	Near front of NE corner TS 328, mobile	90 day	decon water with oxidizer	No
MMH3	a	300	Near front of NE corner TS 328, mobile	90 day	decon water with fuel	No
MMH4	a	300	Near front of NE corner TS 328, mobile	90 day	decon water with fuel	No
300 HCU	a	300	southeast corner of HCU in secondary containment	sa	used oil and oil contaminated rags	No
302 POND	a	300	northwest corner of 302 Pond	sa	holes floor oxide and floor from pond clean up	No
TS 411	a	400	East of support Building 412	90 day	decon water with oxidizer	No
ST PAD	a	400	South of decon pad, East of Building 448	sa	IPA, vacuum pump oil	No
400 VPO	a	400	East of Building 411	sa	vacuum pump oil	No
400 OX BAR	a	400	Decon sink between Buildings 415 & 416	90 day	decon water with oxidizer	Yes
400 FUEL BAR	a	400	Decon sinks between Buildings 415 & 416	90 day	decon water with fuel	Yes
400 90 DAY	a	400	East of support Building 412	90 day	decon water with fuel	Yes
400 RAGS	a	400	400 area N sink removed area	sa	solvent contaminated rags	No
FTU	a	500	NASA Road P NE of 300 Area	nw	slush waste (permitted)	Yes
IDW	a	600	Near trailers south of Bldg. 658	90 day	IDW	No
MPE-16 A	a	600	west side of storage pool	sa	contaminated debris	No
MPE-16 B	a	600	southeast corner of well pad	sa	well development sediment	No
BLDG 650	a	600	southeast corner inside Building 650	sa	contaminated debris	No
HFTA	a	800	West of 800, outside ket cells	90 day	fuel contaminated water, fuel contaminated soft goods	Yes
PREP LAB	a	800	Building 804 - North wall	sa	petroleum contaminated material	No

