



Pre-cover installation
Excavation backfilled to 4 ft bgs



Post-cover installation
Drainage swales/revegetation not completed
Restoration of asphalt road in progress

840857.01100000 A7

Figure 7
Panoramic Photographs of the CWL Prior to and After Cover Installation