



NEW MEXICO
ENVIRONMENT DEPARTMENT

DOE Oversight Bureau

MICHELLE LUJAN GRISHAM
Governor

HOWIE C. MORALES
Lt. Governor

121 Tijeras Ave., NE Suite 1000
Albuquerque, NM
Phone (505) 383-2073 Fax (505) 222-9510
www.env.nm.gov



JAMES C. KENNEY
Cabinet Secretary

JENNIFER PRUETT
Deputy Secretary

June 7, 2019

Victoria Branson
Point of Contact
Water Quality Program Manager
U.S. Department of Energy
Sandia Field Office
P.O Box 5400 MS 0184
Albuquerque, New Mexico 87185-5400

Subject: Data Submittal for Groundwater Monitoring at Sandia National Laboratories/New Mexico Tijeras Arroyo Groundwater Area of Concern Conducted by the New Mexico Environment Department DOE Oversight Bureau for FFY 2019 Q-2

Ms. Branson:

This letter transmits the subject report as final. The report shows groundwater data results from Sandia National Laboratories Tijeras Arroyo Groundwater Area of Concern conducted by the New Mexico Environment Department DOE Oversight Bureau during the second quarter of FFY 2019.

The enclosed monitoring results were provided to the U.S Department of Energy in draft form on May 6, 2019 for 30-day review and comment. The final monitoring results are provided to DOE, the State of New Mexico and other federal agencies, the NMED website and interested members of the public. If you have any questions, or if you would like copies of the complete data set, please contact me by phone at (505) 383-2070, by email at chris.armijo1@state.nm.us, or by mail to the address in the above letterhead.

Sincerely,

A handwritten signature in blue ink that reads "Chris Armijo".

Chris Armijo
Environmental Scientist
Sandia Oversight Section

Enclosure: (1) Groundwater Monitoring at Sandia National Laboratories/New Mexico Tijeras Arroyo Groundwater Area of Concern Conducted by the New Mexico Environment Department DOE Oversight Bureau for FFY 2019 Q-2
(2) Table-1 Nitrate-Nitrite as Nitrogen Results
(3) Table-2 Detected Volatile Organic Compounds Results
(4) Table-3 Method Detection Limit for Volatile Organic Compounds

Distribution: David Rast, DOE/SFO
Michael Skelly, SNL/NM
Tim Jackson, SNL/NM
Beau Masse, NMED DOE-OB
Susan Lucas-Kamat, NMED DOE-OB

File: SGE42. Groundwater Monitoring. TAG AOC. FFY 2019 Q-2

DOE Oversight Bureau, New Mexico Environment Department

**Groundwater Monitoring at
Sandia National Laboratories/New Mexico
Tijeras Arroyo Groundwater Area of Concern**

**Conducted by the
New Mexico Environment Department
DOE Oversight Bureau
for FFY 2019 Q-2**

**Prepared by Chris Armijo, Environmental Scientist
Sandia Oversight Section
121 Tijeras Ave., NE Suite 1000
Albuquerque, NM 87102
(505) 383-2070
chris.armijo1@state.nm.us**

Final Report

6/7/2019

The purpose of this communication is to transmit groundwater quality data collected by the New Mexico Environment Department DOE Oversight Bureau from Sandia National Laboratories Tijeras Arroyo Groundwater Area of Concern during the second quarter of Federal Fiscal Year 2019.

Acknowledgment:

This material is based upon work supported by the Department of Energy Office of Environmental Management under Award Number *DE-EM0002420*.

Disclaimer:

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or usefulness of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

Introduction

The New Mexico Environment Department (NMED) DOE Oversight Bureau (DOE-OB or Bureau) has compiled and assessed groundwater data collected during February and March 2019. The Bureau collected groundwater samples from Tijeras Arroyo Groundwater (TAG) Area of Concern (AOC) monitoring wells TA1-W-06, TA2-W-19, TA2-W-26, TA2-W-27, TA2-W-28, TJA-2, TJA-3, TJA-4, TJA-6 and TJA-7. Groundwater samples were collected using standard Sandia National Laboratories/New Mexico (SNL/NM) sampling procedures and equipment. Samples were analyzed for nitrate-nitrite as nitrogen and target compound list (TCL) volatile organic compounds (VOCs). The Bureau submitted samples for analysis to an independent analytical laboratory under contract with the NMED. Nitrate levels exceeded the U.S. Environmental Protection Agency (EPA) maximum contaminant level (MCL), or drinking water standard of 10 mg/L in samples collected from TAG monitoring wells TA2-W-19, TA2-W-28, TJA-2, TJA-4 and TJA-7.

Data Assessment

All groundwater samples were collected and analyzed in accordance with U.S. Environmental Protection Agency (EPA) protocols. Data results are compared to applicable maximum contaminant levels MCLs established by the U.S. EPA National Primary Drinking Water Regulations (40 CFR 141), National Primary Drinking Water Standards, EPA, July 2002.

Results

Analytical results for nitrate-nitrite as nitrogen are listed in Table-1. Nitrate-nitrite concentrations exceeded the EPA MCL of 10 mg/L from samples collected at monitoring wells TA2-W-19 (11 mg/L), TA2-W-28 (16 mg/L), TJA-2 (11 mg/L), TJA-4 (29 mg/L) and TJA-7 (21 mg/L).

Volatile organic compounds detected at concentrations above the method detection limits (MDLs) are presented in Table-2. The VOCs detected at low concentrations include: dichloroethane [1,1-], dichloroethene [1,1-], dichloroethene [cis-1,2-], tetrachloroethene (PCE) and trichloroethene (TCE). No VOCs were detected above their associated drinking water standards. Table-3 summarizes the laboratory MDLs for the remaining VOCs analyzed from the samples collected at TAG AOC.

Conclusion

The DOE-OB collected groundwater samples from a total of ten (10) TAG AOC monitoring wells during FFY 2019 Q-2. No parameters were detected above EPA drinking water standards, except for nitrate-nitrite as nitrogen at monitoring wells TA2-W-19, TA2-W-28, TJA-2, TJA-4 and TJA-7. Nitrate has been identified as a

contaminant of concern and results compare well to historical nitrate concentrations.

The DOE-OB will continue to independently monitor for contaminants of concern at TAG AOC and make the data reports available to the public.

Table-1

Groundwater Quality Monitoring Results: Nitrate-Nitrite as Nitrogen
 Sandia National Laboratories/New Mexico: Tijeras Arroyo Groundwater Area of Concern
 New Mexico Environment Department DOE Oversight Bureau
 February and March 2019

Monitoring Well/ Sample Date	Analyte	Result (mg/L)	Laboratory Detection Limit (mg/L)	Method Detection Limit (mg/L)	EPA MCL (mg/L)	Laboratory Qualifier	Analytical Method
TA1-W-06 15-Feb-19	Nitrate-Nitrite as Nitrogen	3.3	0.1	0.03	10		EPA: 353.2
TA2-W-19 27-Feb-19	Nitrate-Nitrite as Nitrogen	11	0.1	0.03	10		EPA: 353.2
TA2-W-26 20-Feb-19	Nitrate-Nitrite as Nitrogen	6	0.1	0.03	10		EPA: 353.2
TA2-W-27 18-Feb-19	Nitrate-Nitrite as Nitrogen	3.9	0.1	0.03	10		EPA: 353.2
TA2-W-28 28-Feb-19	Nitrate-Nitrite as Nitrogen	16	0.1	0.03	10		EPA: 353.2
TJA-2 21-Feb-19	Nitrate-Nitrite as Nitrogen	11	0.1	0.03	10		EPA: 353.2
TJA-3 14-Feb-19	Nitrate-Nitrite as Nitrogen	2.6	0.1	0.03	10		EPA: 353.2
TJA-4 4-Mar-19	Nitrate-Nitrite as Nitrogen	29	0.2	0.06	10		EPA: 353.2
TJA-4 4-Mar-19 (Duplicate)	Nitrate-Nitrite as Nitrogen	29	0.2	0.06	10		EPA: 353.2
TJA-6 13-Feb-19	Nitrate-Nitrite as Nitrogen	2.4	0.1	0.03	10		EPA: 353.2
TJA-7 1-Mar-19	Nitrate-Nitrite as Nitrogen	21	0.2	0.06	10		EPA: 353.2

Bold = Data results exceed the established EPA MCL.

Table-2

Groundwater Quality Monitoring Results: Detected Volatile Organic Compounds
 Sandia National Laboratories/New Mexico: Tijeras Arroyo Groundwater Area of Concern
 New Mexico Environment Department DOE Oversight Bureau
 February and March 2019

Monitoring Well/ Sample Date	Analyte	Result (µg/L)	Laboratory Detection Limit (µg/L)	Method Detection Limit (µg/L)	EPA MCL (µg/L)	Laboratory Qualifier	Analytical Method
TA1-W-06 15-Feb-19	Dichloroethene[1,1-]	1.1	1	0.3	7		SW846: 8260B
TA2-W-19 27-Feb-19	Dichloroethane[1,1-]	0.31	1	0.3	NE	J	SW846: 8260B
	Dichloroethene[cis-1,2-]	0.43	1	0.3	70	J	SW846: 8260B
	Trichloroethene	2.5	1	0.5	5		SW846: 8260B
TA2-W-26 20-Feb-19	Dichloroethene[cis-1,2-]	0.53	1	0.3	70	J	SW846: 8260B
	Tetrachloroethene	1.2	1	0.3	5		SW846: 8260B
	Trichloroethene	1.4	1	0.5	5		SW846: 8260B
TA2-W-27 18-Feb-19	Dichloroethene[1,1-]	0.3	1	0.3	7	J	SW846: 8260B
	Tetrachloroethene	1.6	1	0.3	5		SW846: 8260B
	Trichloroethene	1.2	1	0.5	5		SW846: 8260B
TJA-2 21-Feb-19	Dichloroethane[1,1-]	0.45	1	0.3	NE	J	SW846: 8260B
	Dichloroethene[cis-1,2-]	0.6	1	0.3	70	J	SW846: 8260B
	Trichloroethene	4.5	1	0.5	5		SW846: 8260B
TJA-7 1-Mar-19	Trichloroethene	3.2	1	0.5	5		SW846: 8260B

J = The reported value was obtained from the reading that was less than the Reporting Limit but greater than or equal to the Method Detection Limit (MDL).

NE = Not Established

Table-3

Groundwater Quality Monitoring Results: Method Detection Limits for Volatile Organic Compounds by Method SW846:8260B
 Sandia National Laboratories/New Mexico: Tijeras Arroyo Groundwater Area of Concern

New Mexico Environment Department DOE Oversight Bureau

February and March 2019

Analyte	Method Detection Limit (µg/L)
Acetone	3
Benzene	0.3
Bromobenzene	0.3
Bromochloromethane	0.3
Bromodichloromethane	0.3
Bromoform	0.3
Bromomethane	0.33
Butanone[2-]	3
Butylbenzene[n-]	0.3
Butylbenzene[sec-]	0.3
Butylbenzene[tert-]	0.3
Carbon Disulfide	0.3
Carbon Tetrachloride	0.15
Chlorobenzene	0.3
Chlorodibromomethane	0.3
Chloroethane	0.3
Chloroform	0.3
Chlorohexane[1-]	0.3
Chloromethane	0.3
Chlorotoluene[2-]	0.3
Chlorotoluene[4-]	0.3
Dibromo-3-Chloropropane[1,2-]	0.6
Dibromoethane[1,2-]	0.3
Dibromomethane	0.3
Dichlorobenzene[1,2-]	0.3
Dichlorobenzene[1,3-]	0.3
Dichlorobenzene[1,4-]	0.3
Dichlorodifluoromethane	0.3
Dichloroethane[1,1-]	0.3
Dichloroethane[1,2-]	0.15
Dichloroethene[1,1-]	0.3
Dichloroethene[cis-1,2-]	0.3
Dichloroethene[trans-1,2-]	0.3
Dichloropropane[1,2-]	0.3
Dichloropropane[1,3-]	0.15

Analyte	Method Detection Limit (µg/L)
Dichloropropane[2,2-]	0.3
Dichloropropene[1,1-]	0.3
Dichloropropene[cis-1,3-]	0.3
Dichloropropene[trans-1,3-]	0.3
Ethylbenzene	0.3
Hexachlorobutadiene	0.3
Hexanone[2-]	3
Iodomethane	0.3
Isopropylbenzene	0.3
Isopropyltoluene[4-]	0.3
Methyl tert-Butyl Ether	0.3
Methyl-2-pentanone[4-]	3
Methylene Chloride	0.34
Naphthalene	0.3
Propylbenzene[1-]	0.3
Styrene	0.3
Tetrachloroethane[1,1,1,2-]	0.3
Tetrachloroethane[1,1,2,2-]	0.3
Tetrachloroethene	0.3
Toluene	0.3
Trichloro-1,2,2-trifluoroethane[1,1,2-]	0.3
Trichlorobenzene[1,2,3-]	0.3
Trichlorobenzene[1,2,4-]	0.3
Trichloroethane[1,1,1-]	0.3
Trichloroethane[1,1,2-]	0.3
Trichloroethene	0.5
Trichlorofluoromethane	0.3
Trichloropropane[1,2,3-]	0.3
Trimethylbenzene[1,2,4-]	0.3
Trimethylbenzene[1,3,5-]	0.3
Vinyl acetate	0.73
Vinyl Chloride	0.15
Xylene[1,2-]	0.3
Xylene[1,3-]+Xylene[1,4-]	0.3